Dart Aerospace Ltd. Thursday, 7/12/2007 10:39:33 AM Kim Johnston **Process Sheet** : DOOR DOUBLER : CU-DAR001 Dart Helicopters Services **Drawing Name** Customer Job Number : 33524 12942 **Estimate Number** : D3594044 **Part Number** P.O. Number A/4: .01.0.2 D3594 REV A 7/12/2007 **Drawing Number** This Issue : N/A Project Number Prsht Rev. : SMALL /MED FAB **Drawing Revision** First Issue Type Material Previous Run : 7/17/2007 Each Qty: 4 Um: **Due Date** Written By Checked & Approved By New Issue 07-01-22 EC Comment **Additional Product** Job Number: Description: Seq. #: 6061-T6 .080 Sheet M6061T6S080 1.0 Comment: Qtv.: Total: 2.1420 sf(s) 0.5355 sf(s)/Unit 6061-T6 .080 Sheet Batch: W 2.0 WATER JE Comment: FLOW WATER JET 1-Cut as per Dwg D3594 Dwg Rev: A Prog Rev: ___________ 2-Deburr if necessary 3.0 QC2 ES Comment: INSPECT PARTS AS THEY COME OFF MACHINE 4.0 SECOND CHECK QC8 Comment: SECOND CHECK SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 1 5.0

Comment: SMALL & MEDIUM FAB RESOURCE 1 C'SINK AS PER DWG D3594



W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
		•									
				· · · · · · · · · · · · · · · · · · ·							
		•									

Part No: D3594-044 PAR #: NA. Fault Category: Prop- Swinced NCR: Yes No DQA: Date: 07.07.18

QA: N/C Closed: 4 Date: 07.01.23

NCR:3	3524	f w	ORK OR	DER NON-CONFORMANC	E (NCR)	C)	 .
DATE	STEP	Description of NC . Section A	Initial Chiev Eng	Corrective Action Section B Action Description Chief Eng	Sign &	Verification Section C	Approval Chief Eng	Approval QC Inspecto
ભીગૃા	₹ V_	Stoppy and overlives the hole RC thuman Error	POSIULZ	-fil hole with willD grad fluch transferdr.U	Mg 07-16	En OHOHU	TOSIU12	En Ald,
			47042	KS attratcled commil.			Ja asnoan	,

NOTE: Date & initial all entries

Thursday, 7/12/2007 10:39:33 AM Date: Use_j; Kim Johnston **Process Sheet** Drawing Name: DOOR DOUBLER Customer: CU-DAR001 Dart Helicopters Services Part Number: D3594044 Job Number: 33524 Job Number: Description: Seq. #: Machine Or Operation: INSPECT WORK TO CURRENT STEP 6.0 QC5 Comment: INSPECT WORK TO CURRENT STEP HAND FINISHING1 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 8.0 QC3 01-07-17 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: Qty.: 1.0000 Each(s)/Unit Total: 4.0000 Each(s) Anchor nuts 10.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 8.0000 Each(s) Rivet mios) BATCH: SMALL & MEDIUM FAB RESOURCE 1 11.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 Install Nut Plates As per Dwg D3594 INSPECT WORK TO CURRENT STEP 12.0 QC5 Comment: INSPECT WORK TO CURRENT STEP 13.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location:

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES									
DATE	STEP	STEP PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
								:			
Part No	:	PAR #:	Fault Category:	NCR: Yes	No DQ	A:	Date:				

QA: N/C Closed: ____ Date: ____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	A	A			
DATE STEP		Section A	Initial Action Description Sign & Chief Eng Chief Eng Date		Section C	Approval Chief Eng	Approval QC Inspecto				
 -											

NOTE: Date & initial all entries

Date: User; Thursday, 7/12/2007 10:39:33 AM

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: DOOR DOUBLER

Job Number: 33524

Part Number: D3594044

Job Number:



Seq. #:

Machine Or Operation:

Description:

14.0

QC21

FINAL INSPECTION/W/O RELEASE





Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



U A. A.A.

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
				:							
					٠.						
Part No		PAR #: Fault Category:	NCR: Yes	s No DQ	A:	_ Date: _					
			QA:	N/C Close	d:	Date: _					


NCR:			WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B			Ammerical	T			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector			
·											
								-			


NOTE: Date & initial all entries



	1		1		
DESIG		DRAW	ВҮ		EROSPACE LTD
لا ا	13	1 1	3	HAWKESBL	JRY, ONTARIO, CANADA
CHECK	ED	APPRO	VED /	DRAWING NO.	REV. A
	-11			D3594	SHEET 1 OF 3
DATE				TITLE	SCALE
	07.0)4.13		DOUBLER	1:1
REV		DATE		D	ESCRIPTION
Α		07	.04.13	NEW ISSUE	








D3594-041 DOOR DOUBLER ASSEMBLY 🐴

QTY -041	P/N	DESCRIPTION			
X	D3594-041	DOOR DOUBLER ASSEMBLY			
1	D3594-1	DOOR DOUBLER			
1	MS21069-5	ANCHOR NUT			
2	MS20426AD4-4	RIVET			



D3594-1 DOOR DOUBLER 1 2

NOTES: 1) MATERIAL: 6061-T6 (OR 6061-T62) ALUMINUM SHEET, 0.080 THICK,

SHOP COPY RETURN TO ENGINEERING

UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE

WORK ORDER

(REF. DART SPEC. M6061T6S.080)
2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1

3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

PER AMS-QQ-A-250/11 OR AMS 4025 OR AMS 4027

4) IDENTIFY WITH DART P/N "D3594-041" USING FINE POINT PERMANENT INK MARKER

5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED

6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX

COPYRIGHT © 2007 BY DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



	l		L		
DESIGN		DRAWN	BY	DART AFR	OSPACE LTD
	3		3		ONTARIO, CANADA
CHECKE	Dall	APPRO\	/ED _y /	DRAWING NO.	REV. A
-	#	•	TH	D3594	SHEET 2 OF 3
DATE				TITLE	SCALE
07.04.13				FLOOR DOUBLE	ER ASSEMBLY 1:3



MS21069-5 M 104214 ! ANCHOR NUT

D3594-043 FLOOR DOUBLER ASSEMBLY (D3594-044 OPPOSITE)

QTY -043	QTY -044	P/N	DESCRIPTION
X		D3594-043	FLOOR DOUBLER ASS'Y, LH
	Х	D3594-044	FLOOR DOUBLER ASS'Y, RH
1		D3594-3	FLOOR DOUBLER, LH
	1	D3594-4	FLOOR DOUBLER, RH
1	1	MS21069-5	ANCHOR NUT
2	2	MS20426AD4-4	RIVET

SHOP COPY RETURN TO **ENGINEERING** INCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE WORK ORDER

NOTES:

1) MATERIAL: 6061-T6 (OR 6061-T62) ALUMINUM SHEET, 0.080 THICK, PER AMS-QQ-A-250/11 OR AMS 4025 OR AMS 4027

(REF. DART SPEC. M6061T6S.080)

2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1


3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED


4) IDENTIFY WITH DART P/N "D3594-043/-044" USING FINE POINT PERMANENT INK MARKER

5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX



	- 1		i		
DES	SIGN	DRAWN	BY	DART AE	ROSPACE LTD
1	13	A	3	, HAWKESBUR	Y, ONTARIO, CANADA
CHI	CKED	APPRO	VED,/	DRAWING NO.	REV. A
1			#	D3594	SHEET 3 OF 3
DAT	E			TITLE	SCALE
	07.04.13			DOUBLER	1:3





D3594-3 FLOOR DOUBLER (D3594-4 OPPOSITE)

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER

NO.____

COPYRIGHT © 2007 BY DART AEROSPACE LTD

, (ŧ					
DART, AEROSPACE LTD					Work Order:	33524 D 3694-694 Page 1 of 1	
Description: POOR DOUBLER LH				Part Number:			
Inspection Dwg: Rev: A							
	FIRST A	ARTICLE IN	SPECTION	ON CHE	CKLIST		
		First Article		Prototype		•	
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments	
12.24	4030	12.24	×				
7.85	4030	7.85	×				
7.313	7/- 1010	7,313	¥				
884.6	+1010	2.687	X				
Ø .323	+.006001	334)				
0 .129	+.006001	. 129	×				
.359	+/- ,010	:3					
.718	1/010	.718	¥ .			h	
. 81	4/030	,81	X				
2.35	7/630	2.36	¥				
R 306	7/- the 030						
R200/	19-	MAN	DAN	MOT A	ENCORE	$1 \wedge$	
R 1.06	7	NYA		TI		<u> </u>	
	`						
		 					

Measured by:	iR	Audited by:	Prototype Approval:	
Date:	07-07-(3	Date: 07/07/16	Date:	10/12

Rev	Date	Change	0,	Revised by	Approved
A	Date	New Issue	10 - 044	KJ/RF	



Jason Murdoch

From: David Shepherd [dshepherd@dartaero.com]

Sent: Wednesday, July 18, 2007 3:45 PM

To: 'Jason Murdoch'

Cc: 'L Lacelle'
Subject: RE: NCR's

As these parts are for the D412-698-023 Door Opener Kit and the rivet holes are used to install a nutplate, the rework you have outlined below is acceptable to me.

David

From: Jason Murdoch [mailto:jmurdoch@dartaero.com]

Sent: Wednesday, July 18, 2007 11:35 AM

To: 'David Shepherd' Subject: NCR's

Good afternoon. I had 4x D3594-043 doublers B33523, and 4x D3594-044 doublers B33524, that needed to be re-worked. For the -044, 2 parts were incorrectly counter sunk, resulting in the hole being slightly over sized. For the -043, 1 part was counter sunk too deep, which would have resulted in a bad assembly, meaning in correct riveting (a tiny gap between the material, and the rivet head). I had the parts re-worked by filling the holes necessary with weld, seeing as how the material was 6061-T6, and ground flush to the surface, then transfer drilled too the drawing. The hole sizes were only 0.129". Is this acceptable to you?

jmurdoch@dartaero.com Q.C. COORDINATOR

No virus found in this incoming message.

Checked by AVG Free Edition.

Version: 7.5.476 / Virus Database: 269.10.8/906 - Release Date: 7/17/2007 6:30 PM

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.476 / Virus Database: 269.10.8/906 - Release Date: 7/17/2007 6:30 PM